



CorrosionCOPS

When it's Rust Call US!

CASE HISTORY

Enviroklean Stain CarWell CP90/Rust Cop

Date

March 30, 2015

Customer

C&C Honolulu—Liberty Bell

Location

Honolulu, Hawaii, USA

Problem

C&C Honolulu has historic Liberty Bell of Aloha mounted on white concrete pedestal. The pedestal was repainted December 2014 and already the metal plate was bleeding unsightly rust stains down the sides of the pedestal. Left as is—the staining would get larger and darker and shorten the life of the paint. Not to mention an eyesore as this historic bell is located right next to City and County of Honolulu main building.

Solution and Procedure

1. Apply Enviroklean Stain Remover by rag or brush.
2. Rinse with fresh water.
3. Apply CarWell CP90/Rust Cop to all exposed metal surfaces.

Conclusion

Use of environmentally friendly, water based Enviroklean Stain Remover easily removed the rust staining on the painted surface and applying CarWell Rust Cop rust inhibitor will provide further corrosion protection to metal plate. Follow up maintenance required on yearly basis.



Before



After

Solutions for Rust and Corrosion

94-463 Alapine Street, Waipahu, Hawaii 96797 Phone (808) 676-1963 Fax (808) 678-1677 www.corrosioncops.com